

F1000 Quick Reference Chart

Modality	Main Display On/Off	Sound On/Off	Other Settings	Range	Sound Threshold
Temperature 1 (Temperature2 use <ctrl>)	F9	F8	Ruler F4 Circle F5 Digit F6 Sound Reverse F7	Ruler Range F2 (-), F3 (+) Ruler Zero F1 Ruler Autozero F11	
EDR	<alt> F9	<alt> F8	% Bar <alt> F4 Num Bar <alt> F5 Digit <alt> F6	Bar <alt> F2(-), <alt> F3 (+) Bar Zero <alt> F1 Bar Autozero <alt> F11	
EMG1 EMG2 Use <alt>	Del	5	Filters <ctrl><shft> F1-F12	Scale: Left Arrow (-), Right Arrow (+)	Up, Dn Arrow PgUp, PgDn
EnhEnh Mode	Del	5	Filters <ctrl><shft> F1-12 Raw Logging On/Off <Ins>	Scale: Left Arrow (-), Right Arrow (+)	Up, Dn Arrow PgUp, PgDn
InhEnh Mode		5	Oval On/Off <End> Counter On/Off <alt ><End> Counter Reset <Home>	Scale: Left Arrow (-), Right Arrow (+)	Up, Dn Arrow PgUp, PgDn
Tansey		5	Filters <ctrl><shft> F1-F8 FFT Bars On/Off <ctrl><Shft> F11 FFT/Analog <ctrl><Shft> F12	Scale: Left Arrow (-), Right Arrow (+)	Up, Dn Arrow PgUp, PgDn
MAT		5	Filters <ctrl><shft> F1-F9 Bars On/Off <ctrl><Shft> F11 FFT/Analog <ctrl><Shft> F12 Seq On/Off <End> Auto On/Off <Home>	Scale: Left Arrow (-), Right Arrow (+)	Up, Dn Arrow PgUp, PgDn

Start Up: **BIO2**
 Save Data : <Alt> S
 Quit Most: <alt> Q

Sound Volume: Numeric **Plus, Minus** keys

Event Markers: **1,2,3,4,spacebar, Tova Button**
 Multimodal screen Displays: <Alt> **1,2,3**